

AD-A069 227


NEW JERSEY STATE DEPT OF ENVIRONMENTAL PROTECTION TRENTON F/6 13/2
NATIONAL DAM SAFETY PROGRAM. ASSUNPINK DAM, NUMBER 19. (NJ00453--ETC(U)
APR 79 F K JOLLS


DACW61-78-C-0124

NL

UNCLASSIFIED

1 OF 1
AD
A069227





AD A069227

DDG
QUALITY
INSPECTED
1

DELAWARE RIVER BASIN
ASSUNPINK CREEK
MONMOUTH COUNTY
NEW JERSEY

LEVEL

ASSUNPINK DAM

NO.19

NJ 00453

6 PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM.

Assunpink Dam, Number 19. (NJ00453).
Delaware River Basin. Assunpink Creek,
Monmouth County, New Jersey. Phase 1
Inspection Report.

Approved for public release;
distribution unlimited

DDC FILE COPY

THIS DOCUMENT IS BEST QUALITY PRACTICE
AND COPY FURNISHED TO DDC CONTAINED A
SIGNIFICANT NUMBER OF PAGES WHICH
REPRODUCE FAULTY.



9 Final rept.

10 F. Keith /Jolls

15 DACW61-78-C-0124

DEPARTMENT OF THE ARMY

Philadelphia District
Corps of Engineers
Philadelphia, Pennsylvania

DDC

JUN 1 1979

12 71p
11 Apr 1979

410894 79 05 21 121

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DDC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

DO FORM 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

NOTICE

**THIS DOCUMENT HAS BEEN REPRODUCED
FROM THE BEST COPY FURNISHED US BY
THE SPONSORING AGENCY. ALTHOUGH IT
IS RECOGNIZED THAT CERTAIN PORTIONS
ARE ILLEGIBLE, IT IS BEING RELEASED
IN THE INTEREST OF MAKING AVAILABLE
AS MUCH INFORMATION AS POSSIBLE.**



DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
CUSTOM HOUSE - 2 D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

IN REPLY REFER TO

NAPEN-D

Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, New Jersey 08621

ACCESSION BY	
DTIC	White Section <input checked="" type="checkbox"/>
DDI	Staff Section <input type="checkbox"/>
UNCLASSIFIED	<input type="checkbox"/>
JUSTIFICATION	
BY	
DISTRIBUTION/AVAILABILITY CODES	
Dist. AVAIL. and/or SPECIAL	
A	23 JY

7 MAY 1979

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Assunpink Dam No. 19 in Monmouth County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Assunpink Dam No. 19, initially listed as a high hazard potential structure but reduced to a low hazard potential structure as a result of this inspection, is judged to be in good overall condition and the spillway is considered adequate. The low hazard potential classification means that in the event of failure of the dam, no loss of life and only minimal economic loss is expected. However, to assure the continued functioning of the dam and its impoundment, the following remedial actions could be undertaken:

- a. Repair and seed eroded areas on all slopes.
- b. Place additional barriers at access points around the perimeter of the dam to prevent erosion caused by unauthorized vehicular use of the dam surfaces.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Frank Thompson, Jr. of the Fourth District. Under the provisions of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.


NAPEN-D

Honorable Brendan T. Byrne

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dam Safety Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed action taken by the State to implement our recommendations.

Sincerely,



JAMES G. TON
Colonel, Corps of Engineers
District Engineer

1 Incl
As stated

Copies furnished:

Dirk C. Hofman, P.E., Deputy Director
Division of Water Resources
N. J. Dept of Environmental Protection
P. O. Box CN029
Trenton, NJ 08625

John O'Dowd, Acting Chief
Bureau of Flood Plain Management
Division of Water Resources
N. J. Dept. of Environmental Protection
P. O. Box CN029
Trenton, NJ 08625


ASSUNPINK DAM NO. 19 (NJ00453)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 4 January 1979 by Louis Berger and Associates, Inc. under contract to the State of New Jersey. The state, under agreement with the U. S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Assunpink Dam No. 19, initially listed as a high hazard potential structure but reduced to a low hazard potential structure as a result of this inspection, is judged to be in good overall condition and the spillway is considered adequate. The low hazard potential classification means that in the event of failure of the dam, no loss of life and only minimal economic loss is expected. However, to assure the continued functioning of the dam and its impoundment, the following remedial actions could be undertaken:

- a. Repair and seed eroded areas on all slopes.
- b. Place additional barriers at access points around the perimeter of the dam to prevent erosion caused by unauthorized vehicular use of the dam surfaces.

APPROVED: 

JAMES G. TON
Colonel, Corps of Engineers
District Engineer

DATE: 7 May 1979


PHASE I REPORT
NATIONAL DAM INSPECTION PROGRAM


Name of Dam Assunpink Dam No. 19 Fed ID# NJ 00453
NJ ID# 594


State Located New Jersey
County Located Monmouth
Coordinates Lat. 4012.3 - Long. 7429.5
Stream Assunpink Creek
Date of Inspection 4 January 1979

ASSESSMENT OF
GENERAL CONDITIONS

Assunpink Dam No. 19 is in a good overall condition and has sufficient spillway capacity to accommodate the 100-year design flood. It is recommended that its hazard classification be downgraded to low as it is situated within an official Fish and Wildlife Management Area and overtopping or collapse would not appreciably increase the danger of loss of life or property damage. No detrimental findings were uncovered to merit further study. Recommended remedial actions to be undertaken in the future as part of the State maintenance program include repair and seeding of the eroded areas of all slopes and placing additional vehicular barriers at the accessible points around the perimeter of the dam.


F. Keith Jolls P.E.
Project Manager





OVERVIEW OF ASSUNPINK CREEK WATERSHED DAM SITE #19

DECEMBER, 1978

TABLE OF CONTENTS

	<u>Page</u>
Assessment of General Conditions	
Overall View of Dam	
Table of Contents	
Preface	
Section 1 - Project Information	1-5
Section 2 - Engineering Data	6-7
Section 3 - Visual Inspection	8-10
Section 4 - Operational Procedures	11-12
Section 5 - Hydraulic/Hydrologic	13-14
Section 6 - Structural Stability	15-16
Section 7 - Assessment/Recommendations/ Remedial Actions	17-18

FIGURES

Figure 1 - Regional Vicinity Map	
Figure 2 - Management Area Overview	
Figure 3 - General Plan	
Figure 4 - Typ. Section of Embankment	
Figure 5 - Profile Along Centerline of Principal Spillway	

APPENDIX

Check List - Visual Inspection	
Check List - Engineering Data	
Photographs	
Check List - Hydrologic and Hydraulic Data	
Computations	A1-A19

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM
NAME OF DAM: ASSUNPINK DAM SITE NO. 19 FED #NJ00453
AND NJ ID #594

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority

This report is authorized by the Dam Inspection Act, Public Law 92-367, and has been prepared in accordance with Contract FPM-36 between Louis Berger & Associates, Inc. and the State of New Jersey and its Department of Environmental Protection, Division of Water Resources. The State, in turn, is under agreement with the U.S. Army Corps of Engineers, Philadelphia to have this inspection performed.

b. Purpose of Inspection

The purpose of this inspection is to evaluate the structural and hydraulic condition of the Assunpink Dam No. 19 and appurtenant structures, and to determine if the dam constitutes a hazard to human life or property.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances

The dam at Assunpink Site No. 19 (a/k/a Stone Tavern Lake) is a two zone, 715 foot long earthen structure with an impermeable core and cutoff key. The dam crest is at elevation 164.9 and creates a multi-purpose reservoir on an unnamed branch of Assunpink Creek within the officially designated State Fish and Wildlife Area. The upstream face is protected by riprap between elevations 147 and 159.5. The principal discharge outlet consists of a drop inlet structure containing a two-stage reinforced concrete riser, a 30-inch diameter reinforced concrete outlet pipe, and a reinforced

concrete impact basin. A 75-foot wide trapezoidal auxiliary spillway with a negative approach slope is located at the left abutment. The embankment has a maximum height of 36 feet.

b. Location

The dam is located on an unnamed tributary (which is south of and parallel to the main stream) in the upper reaches of the Assunpink Creek drainage area in Upper Freehold Township, Monmouth County. It is approximately one and three-tenths of a mile southwest of Roosevelt and two and four-tenths miles west of the intersection of county highways 571 and 574 and is located about 2½ miles above Assunpink Dam No. 4. The dam is roughly 6 miles east of Interchange 7A on the N.J. Turnpike.

c. Size Classification

The dam at Site No. 19 has a maximum height of 36 feet and a maximum storage capacity of 1,160 acre-feet. Accordingly, this dam is placed in the intermediate size category as defined by the criteria in the Recommended Guidelines for Safety Inspection of Dams (storage capacity between 1,000 and 50,000 acre-feet).

d. Hazard Classification

This dam is located in a fish and game wildlife area. The only structure between this dam and another larger flood control structure (Site No. 4) downstream is a small secondary road bridge. The downstream flood plain is uninhabited and accordingly, this dam is recommended to be downgraded to a low hazard classification. If this dam should collapse and completely discharge its total storage of 1,160 acre-feet into the reservoir at Dam No. 4, little effect would be felt as Dam No. 4 has a storage capacity of over 3,000 acre-feet above spillway crest and a large auxiliary spillway. Further, there is no development below Dam No. 4.

e. Ownership

This dam is owned by the State of New Jersey, Department of Environmental Protection, Division of Fish, Game, and Shellfisheries, Trenton, New Jersey.

f. Purpose of Dam

The purpose of the dam is floodwater retention, sediment storage, wildlife management, and recreation.

g. Design and Construction History

The dam was designed in 1967 by the United States Soil Conservation Service as part of the Assunpink Creek Watershed floodwater retention program and constructed under the authority of the Watershed Protection and Flood Prevention Act (PL 566). Construction of the dam was completed in 1971 by C.C. Anselman Inc., General Contractors.

h. Normal Operating Procedures

The dam is maintained by personnel of the N.J. Division of Fish and Game but there are no routine, day-to-day, operational procedures performed at this dam. The water level in the lake is regulated during the year at the direction of the Bureau of Fisheries with changes occurring only once or twice a year.

1.3 PERTINENT DATA

a. Drainage Area

Assunpink Site No. 19 has a drainage area of 1.77 square miles which consists of woodland, cropland and meadowland.

b. Principal spillway capacity at dam crest
elevation - 120 cfs

Auxiliary spillway capacity at dam crest
elevation - 1,450 cfs

Total spillway capacity at top of dam - 1,570 cfs

c. Elevations (ft. above MSL)

Top of dam - 164.9
Principal spillway crest - 156.5
Auxiliary spillway crest - 160.9
Streambed at centerline of dam - 129₊

d. Reservoir

Length of maximum design pool (top of dam)
- 5,020 feet

Length of recreation pool (principal spillway
crest) - 4,400 feet

Length of flood control pool (auxiliary spillway
crest) - 4,670 feet

e. Storage (acre-feet)

Recreation pool - 490
Flood control pool - 805
Top of dam - 1,160₊

f. Reservoir Surface (acres)

Top dam - 112.5
Recreation pool - 56
Flood control pool - 86.5

g. Dam

Type - Earth with drop inlet and auxiliary
spillway

Length - 715 feet

Height - 36 feet

Top Width - 15 feet

Side Slopes - 2.5H:1V

Zoning - 2 zones (see attached plans)

Impervious Core - Clayey and silty sand (SC-SM)
compacted to 95% of maximum
dry density.

Cutoff - Keyed section at base of core.

Grout curtain - None

h. Diversion and Regulating Tunnel

Type - None

i. Spillway

Type - Auxiliary channel excavated at left abutment.

Channel width - 75 feet (3H:1V sideslopes)

Gates - None

U/S Channel - Negatively sloped, vegetated inlet

D/S Channel - Positively sloped, vegetated outlet

j. Regulating Outlets

Principal spillway is a 2 stage, drop inlet structure with a 30-inch diameter reinforced concrete outlet pipe and a low water 12"x12" drawdown outlet. Crest El. = 156.5.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

Complete details of the initial design report and work plan, hydraulic determinations, structural analyses and subsurface information were available at the Soil Conservation Service offices (in Somerset) together with as-built plans and records of the various corrective measures undertaken since the initial construction. All design was done in accordance with SCS criteria and was discussed with engineering personnel of their staff who explained in detail the various design and operational features of the dam, particularly the hydraulics of the spillways. The main spillway drop inlet structure is a two-stage deep-well concrete riser of a standard design developed by the Saint Anthony Falls Hydraulic Laboratory. The impact basin is also of a standard design developed by the Bureau of Reclamation. This type of energy dissipator is rather widely used and functions almost completely independent of tailwater head.

2.2 CONSTRUCTION

The construction closely followed the contract plans. The SCS supervised the construction on lands acquired by the Department of Conservation and Economic Development with Green Acres funds. There have been no major structural modifications since the initial construction except in 1977 when additional subsurface drainfill was installed immediately above and along the sides of the impact basin headwall. Stone riprap was also placed on the upstream face at this time.

2.3 OPERATION

As the principal purpose of the dam is to reduce urban flooding in Trenton as well as to establish a wildlife management and recreational area, the multi-purpose operation appears to function properly under the aegis of the Division of Fish and Game who regulate the water level seasonally. (See Section 4 for additional operational information).

2.4 EVALUATION

a. Availability

Sufficient engineering data was obtained to assess the structural stability with regard to the embankment zones. The foundation stability was delineated in the various soils reports prepared by the SCS (which analyzed all geotechnical aspects in considerable detail). The soils at the dam consist of Coastal Plains sediments of glauconitic Navesink sands overlaid by Mount Laurel - Wenonah sands. All overlying organic alluvium was stripped before construction. The stability of the slopes were checked by the Swedish circle method and provided adequate factors of safety. Some concern was expressed at the time of design regarding the permeability of the clean sand beneath the right abutment and the structural behavior of the considerable amount (20,000 + c.y.) of glauconitic sands employed at this site. The SCS soils report states that its behavior as a construction material was unknown in 1967. However, their tests revealed adequate compacted densities, shear strengths and permeability rates and the glauconitic sand was ultimately employed in the core. Shell material was selected from the Red Bank Sand which overlaid the Navesink Formation above the auxiliary spillway.

b. Adequacy

The field inspection and review of the available design plans reveal that the dam is structurally sound and well-built. It is believed that the data available is adequate to render this assessment without recourse to gathering additional information.

c. Validity

The validity of the engineering data available is not challenged and is accepted without recourse to further investigations.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General

Visual inspection of Dam No. 19 was conducted on January 4, 1979 with engineering personnel of the SCS and Division of Fish and Game. The overall condition of the dam was reviewed with its designers who pointed out the localized problem areas and remedial measures that have been undertaken. Water level in the lake at the time of the inspection was at normal pool elevation 156.5 and the tailwater was at elevation 130.7.

b. Dam

In general, the dam appeared to be in good condition. Some light growth was observed on the embankment slopes. The riprap protection of the upstream face of the dam was uniformly distributed and well aligned with the exception of a two foot wide swath directly opposite the principal spillway intake structure. At this location the riprap has been displaced laterally to the sides as well as downslope into the reservoir. This displacement is reportedly the result of vandalism. The embankment is a slightly curved structure lying between two naturally higher abutment zones on each side of the river channel. The dam has numerous prominent vehicular tracks along the crest despite the existence of a transverse steel barrier. These tracks (the results of unauthorized vehicles) extend in a southwesterly direction across the auxiliary spillway and up the left abutment; deep erosion gullies have been cut on the left wall of the spillway. There are several rodent burrows near the right end of the embankment and partially frozen cracks in the embankment surface. The

examination also revealed the existence of numerous small (8" deep x 12" long) surface cracks on the downstream face of the embankment which were located 6 to 10 feet up from the toe. These could be the result of frost action (several small capillary "ice flowers" were noted) or animal burrows. Slightly below the toe seepage was observed emanating at the extremes of the cleared zone. The flow continues along the toe to the discharge channel where, combined with seepage from the filter drain around the impact basin, it has caused considerable erosion and sloughing of the right bank of the discharge channel. This area has previously been backfilled and stabilized with riprap and crushed stone. The eroded area extends to a point a few feet above and behind the right wingwall of the outlet structure. Similar seepage and erosion was noted behind the left wingwall. Seepage issuing from around the impact basin has a high iron precipitate content which is staining the concrete and silting the discharge channel immediately downstream. Discharge from toe drains located at the end of the wingwalls also contained a high percentage of iron. The heavy rust-colored precipitate is probably derived from the iron oxide binder frequently found in the Red Bank sands, which were utilized in the shell material for the embankment and are also found in the nearby left abutment. Higher up the slope of the left embankment seepage was noted emanating from a point about 65 feet downstream from the crest of the dam. The site of this clear flow is roughly at elevation 139.

c. Appurtenant Structures

The main spillway riser tower and outfall are located roughly 135 feet from the left abutment. The upper portion of the 33-foot high reinforced concrete riser and the impact basin are in good condition. There are clear trash racks at each opening and the stem-operated gate is in good working order. Although the location of the intake structure (60 feet offshore) precluded a close visual inspection, the concrete, grates, and trash racks appeared to be in satisfactory condition. It was noted that the wheel to the

gate stem was missing but the representative of the Bureau of Fish and Game advised the inspection team that the wheel is removed to prevent vandalism.

The impact basin also appeared to be in good condition and was functioning as designed. Some light efflorescence was noted where the conduit emerges from the headwall. The grass covered auxiliary spillway is 75 feet wide and appeared in good condition with the exception of the erosion gullies and vehicle tracks previously described. Similar to the main embankment, most of the side slopes have adequate ground cover.

d. Reservoir

Stone Tavern Lake is located in a sparsely developed region. The reservoir is surrounded by gently sloping, wooded banks to the east and west and cultivated fields immediately to the south.

e. Downstream Channel

The area below the dam is undeveloped with the terrain flattening out near the downstream confluence with the main stream of the Assunpink Creek. The flood plain consists of open fields and wooded stands and is all within the wildlife reservation. The natural channel is quite narrow and relatively shallow. The left side of the flood plain rises somewhat more abruptly than the gradual slopes to the right. The only channel restriction between the dam and Assunpink Site No. 4 downstream is the lightly-travelled Cooleys Corner Road bridge.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

Dam No. 19 functions as an integral part of the Assunpink Creek Watershed flood control system, as well as providing a wildlife and recreational area. Operational procedures are governed by the N.J. Division of Fish and Game, Bureau of Fisheries who prescribe changes in the lake level periodically during the year. The regulation is performed by field personnel of the N.J.D.F. & G. who manually adjust the gate opening.

4.2 MAINTENANCE OF DAM

The dam is maintained by personnel of the N.J. Division of Fish and Game whose field office is located a short distance downstream. They are responsible for all aspects of the dam's upkeep and safety including grounds keeping, riprap repair, inlet structure operation and repair, impact basin maintenance and routine patrolling and inspection. A recurring problem appears to be the use of unauthorized vehicles on the dam embankment. They have created deep erodable ruts in the shell material covering both the dam and auxiliary spillway. A barrier has been erected across the crest of the dam to prevent passage, but appears to be only minimally effective. The barrier has been vandalized in the past and replaced. Minor defects such as this are corrected as required, but problems of a more serious nature involving structural aspects are referred to the Soil Conservation Service for additional investigation and remedial action.

4.3 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

No formal warning system exists although personnel of the Division of Fish and Game regularly patrol the dam in conjunction with their other duties.

4.4 EVALUATION OF OPERATIONAL ADEQUACY

A formal inspection is performed by engineering personnel of NJDFG and SCS on an annual basis.

The operational and maintenance procedures are considered to be adequate and efficiently performed. The design inherently provides flood control (and dam protection) without attendant personnel. Consequently, the only operations required are limited to those necessary for recreational and environmental purposes. A warning system is not considered essential since the downstream area is also part of the same wildlife reservation.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

a. Design Data

Based on the criteria in the Recommended Guidelines for Safety Inspection of Dams, the 100-year frequency event was selected as the design storm by the inspecting engineer. Precipitation data was obtained from Technical Paper 40 and NOAA Technical Memorandum NWS Hydro - 35. Storage data and time of concentration were obtained from the Soil Conservation Service design calculations and reviewed in the context of the above inspection criteria. Inflow to the reservoir for the selected 100-year storm was computed utilizing the HEC-1 computer program. This gave a peak inflow to the reservoir of 1,850 cfs. Routing this through the controlled-release reservoir reduced the peak to 140 cfs. The combined spillways have a maximum discharge capacity of approximately 1,570 cfs before overtopping occurs and can therefore accommodate the design flood. The depth of overflow in the auxiliary spillway is less than one foot for the design discharge.

b. Experience Data

The dam was originally designed for a 100-year frequency storm using a time of concentration of 2.5 hours. In the original design, annual flood peak discharges were obtained from USGS records for 1924-58 from gaging data in Trenton and detailed hydraulic analyses, including infiltration studies, were exhaustively performed by the SCS to quantify final design values against the economical apportionment of the dam. The crest elevation was established by routing the proportionate freeboard hydrographs of the 100-year flow (3,650 cfs) at Trenton. The auxiliary spillway height was established so that no design flow (according to SCS procedures) ever reaches the spillway crest; the auxiliary spillway is truly an emergency, safety feature.

c. Visual Observations

With the water at low stage at the time of inspection, approximately 3 cfs was flowing out of the 30" outfall. Visual observations confirmed all the aspects and assumptions of the original design, although it is felt that the subsurface seepage losses through the underlying foundation material are somewhat higher than anticipated.

d. Overtopping Potential

There are no records of the dam having been overtopped and the spillways can easily accommodate the design flood.

e. Drawdown Potential

Using the 12"x12" sluice gate opening at the bottom of the riser tower it would take slightly less than 12 days to dewater the reservoir. There is only a slight possibility that there would be tailwater at the time of drawdown.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations

In view of the relative age of the dam embankment, the well-designed and supervised construction and the continuous maintenance, the dam at Assunpink Site No. 19 is deemed to be in a good overall condition. The upper zones of the recently placed riprap protection show little evidence of subgrade subsidence and the main embankment crest and adjoining cut slopes along the auxiliary spillway are at true design grade and are marred only by vehicular rutting. The inspection team noted the continual maintenance problem of backslope erosion and apparent seepage at the downstream toe. The toe drains in the vicinity of the impact basin appear to be under a continuous, but modest, head. In summary, nothing was visually noted to create or worsen a hazardous condition that cannot be readily maintained or corrected. The only drainage element not visible for inspection was the lower portions of the intake riser.

b. Design and Construction Data

From the review of the soils report recommendations and contract plans for the initial construction, the design appears to be well-engineered, reflect a conservative approach and employs conventional analytical techniques. Based upon the condition of the dam and the hazard classification, it is believed that additional design studies are unnecessary under the purview of PL 92-367.

c. Operating Records

The performance of this structure has been satisfactory since its completion, although certain normal remedial repairs and modifications have been required.

d. Post Construction Changes

There have been no major modifications since the 1977 addition of the riprap protective blanket and the filter drainfill.

e. Seismic Stability

The dam is located in Zone 1 and has negligible potential vulnerability to seismic loadings. Experience of the inspection team indicates that dams in this zone will have adequate stability under dynamic loading conditions if stable under static loading conditions.

SECTION 7 - ASSESSMENTS/RECOMMENDATIONS/ REMEDIAL ACTIONS

7.1 DAM ASSESSMENT

a. Safety

Subject to the inherent limitations of the Phase I visual inspection, Assunpink Dam No. 19 is judged to be in a good overall condition. Overtopping of the dam is a very remote possibility and no seriously detrimental conditions were observed. The dam is recommended to be reclassified in a low hazard category due to location within the State Fish and Wildlife Management area.

b. Adequacy of Information

The information made available by the Soil Conservation Service is deemed to be adequate regarding the analyses and evaluation of safe operation and structural stability.

c. Urgency

No immediate urgency is attached to implementing any further studies or the remedial measures set forth below.

d. Necessity for Further Study

In view of the overall condition of this dam and the fact that it is continually monitored by trained engineering personnel, additional inspections under the purview of P.L. 92-367 are deemed to be unnecessary. The Division of Fish and Game, in conjunction with SCS engineers, maintain an internal system of annual inspections and emergency action plans which basically reflect the requirements mandated under P.L. 92-367.

7.2 RECOMMENDATIONS/REMEDIAL MEASURES

a. Recommended Action


Under the current Assunpink Creek Fish and Wildlife Management Area maintenance program,

it is recommended that the following be taken under advisement in the future:

- Regrade the eroded backslopes and sides of the auxiliary channel and reseed the barren areas.
- Continue to monitor the backslope seepage and the subgrade drains which appear to be susceptible to clogging.
- Place additional vehicular barriers at various locations to inhibit the illegal vehicular use on the dam surfaces.

b. O&M Maintenance and Procedures

In view of the assessment contained herein, no additional procedures other than those presently in effect appear to be required.



PROJECT MAP

ASSUNPINK CREEK WATERSHED

MERCER AND MONMOUTH COUNTIES, NEW JERSEY

0 2000' 4000' 6000' 8000'
FEET



- County Line
- Township Line
- City Limits
- Streams
- Railroads

PROJECT MEASURES

- Floodwater retarding structure
- Multiple-purpose structure
- FW - Fish and Wildlife
- R - Recreation






FIGURE 2





TYPICAL SECTION OF EMBANKMENT
 NO SCALE

FIG. 4

Check List
Visual Inspection
Phase 1

Name Dam Assumpink Site #19 County Monmouth State New Jersey Coordinators NJDEP

Date(s) Inspection 1/4, 18/79 Weather Sunny Temperature 15°F

Pool Elevation at Time of Inspection 156.5 M.S.L. Tailwater at Time of Inspection 130.7 M.S.L.

Inspection Personnel:

T. Chapter	F. Schmidt (NJDEG)	K. Jolls
E. Simone	L. Holt (SCS)	
L. Baines		

L. Baines Recorder

Dam No. 00453

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SEE PAGE ON LEAKAGE	N/A	
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	N/A	
DRAINS	N/A	
WATER PASSAGES	N/A	
FOUNDATION	N/A	

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	N/A	
STRUCTURAL CRACKING	N/A	
VERTICAL AND HORIZONTAL ALIGNMENT	N/A	
MONOLITH JOINTS	N/A	
CONSTRUCTION JOINTS	N/A	

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	Minor surface cracks (approximately 12" long) on backslope of right embankment. The crack, approximately 8" deep, may be due to frost heave or animal borrows. Several animal borrows were observed.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed.	
SLOUGHING OR EROSION OF EMBANKMENT AND ADJUTMENT SLOPES	Sloughing behind wingwalls of outlet structure and adjoining channel banks. It has been backfilled and stabilized with riprap. (see photo)	Right wall of auxiliary spillway deeply rutted and eroded by tire tracks.
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Crest rutted with tire tracks despite steel barrier in center of dam crest.	
RIPRAP FAILURES	Riprap displaced from narrow swath directly above 30" outlet pipe. Attributed to vandalism on reservoir side of embankment.	

EMBANKMENT

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

Trees growing along toe of right embankment for about 50' to abutment.

See photographs.

JUNCTION OF EMBANKMENT
AND ABUTMENT, SPILLWAY
AND DAM

Embankment abutments natural terrain on right and auxiliary channel on left. Both sides satisfactory. Tire tracks cross right wall of auxiliary spillway near embankment crest.

ANY NOTICEABLE SEEPAGE

Minor seepage along toe of right embankment beginning at abutment and running along the toe to the outlet structure. (see photo)

Additional seepage about 65' from crest of left embankment. Approximate elevation 139 M.S.L. Pool elevation approximately 156 M.S.L. "Ice flowers" common along embankment.

STAFF GAGE AND RECORDER

None

DRAINS

Toe drains discharging from end of wing-walls of outlet. Heavy precipitate noted here as well as "French drain" around structure.

(See photographs).

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	None observed	Structure in new condition.
INTAKE STRUCTURE	Drop inlet with box riser; gate stem operated. Grating and trash rack on all sides.	All in good condition.
OUTLET STRUCTURE	Reinforced concrete impact basin in front of discharge pipe.	Erosion and sloughing behind wingwalls replaced with riprap. Concrete in good condition. Heavy iron precipitate noted.
OUTLET CHANNEL	Narrow natural channel in wide valley. Heavy tree growths. Some bank sloughing near outlet structure.	Sloughing already backfilled with riprap.
EMERGENCY GATE	None	

UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	None	Auxiliary spillway consists of wide grassy channel abutting left embankment.
APPROACH CHANNEL	Negatively sloped approach, grassy surface. Erosion on both walls of channels. Approximately 3:1 sideslopes.	
DISCHARGE CHANNEL	Positively sloped, vegetated and wooded.	
BRIDGE AND PIERS	None	

GATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	N/A	
APPROACH CHANNEL	N/A	
DISCHARGE CHANNEL	N/A	
BRIDGE AND PIERS	N/A	
GATES AND OPERATION EQUIPMENT	N/A	

INSTRUMENTATION

VISUAL EXAMINATION MONUMENTATION/SURVEYS	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
	TBM2: Railroad spike in 14" ϕ oak tree in downstream channel. El. 135.48.	Others are available.
OBSERVATION WELLS	None	
WEIRS	None	
PIEZOMETERS	None	
OTHER	None	

RESERVOIR

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

SLOPES

Wooded to cultivated. Gently sloping on east, steeper on west.

SEDIMENTATION

None observed. Design provided for dead area on floor of lake to accommodate sedimentation.

See design reports.

10

DOWNSTREAM CHANNEL

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

VISUAL EXAMINATION OF

CONDITION
(OBSTRUCTIONS,
DEBRIS, ETC.)

Gently sloping, wooded area. Wide valley, narrow channel. Many swampy, lowlying marshy areas along channel.

SLOPES

Gentle and wooded.

APPROXIMATE NO.
OF HOVES AND
POPULATION

None in floodplain between this dam and Site #4 downstream.
Part of state wildlife refuge (uninhabited).

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

ITEM	DETAILS
PLAN OF DAM	Available from SCS (1370 Hamilton Street, Somerset, N.J.)
REGIONAL VICINITY MAP	Available from SCS or USGS Quad.
CONSTRUCTION HISTORY	Available from SCS
TYPICAL SECTIONS OF DAM	Available from SCS
HYDROLOGIC/HYDRAULIC DATA	Available from SCS
OUTLETS - PLAN	Available from SCS
- DETAILS	Available from SCS
- CONSTRAINTS	Available from SCS
- DISCHARGE RATINGS	Available from SCS
RAINFALL/RESERVOIR RECORDS	None kept

ITEM	REMARKS
DESIGN REPORTS	Available from SCS
GEOLOGY REPORTS	Available from SCS
DESIGN COMPUTATIONS	Available from SCS
HYDROLOGY & HYDRAULICS	Available from SCS
DAM STABILITY	Not available
SEEPAGE STUDIES	Available
MATERIALS INVESTIGATIONS	Available from SCS
BORING RECORDS	Available from SCS
LABORATORY	Available from SCS
FIELD	Available from SCS
POST-CONSTRUCTION SURVEYS OF DAM	None performed
BORROW SOURCES.	Indicated on available plans

ITEM	REMARKS
MONITORING SYSTEMS	None
MODIFICATIONS	Reports, plans, etc. of modifications and repairs performed in 1976/1977 available from SCS.
HIGH POOL RECORDS	Not recorded
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	Available from SCS as noted above.
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	None
MAINTENANCE OPERATION RECORDS	None kept

ITEM	REMARKS
------	---------

SPILLWAY PLAN


Plans, sections and details for principal and auxiliary spillways available from SCS.

SECTIONS

DETAILS

OPERATING EQUIPMENT
PLANS & DETAILS

Available from SCS.




January, 1979

Assunpink Creek Watershed Dam Site #19




January, 1979

Displaced riprap directly opposite intake structure



January, 1979

Intake structure




January, 1979

Outlet structure



Looking West

January, 1979



Erosion and vehicle tracks

January, 1979



January, 1979

Seepage at toe of right embankment



January, 1979

Repair of sloughed area

CHECK LIST
HYDROLOGIC AND HYDRAULIC DATA
ENGINEERING DATADRAINAGE AREA CHARACTERISTICS: 1.77 sq. milesELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 156.5 (490 acre-feet)ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): 160.9 (805 acre-feet)ELEVATION MAXIMUM DESIGN POOL: + 161.1 M.S.L. (SSC records)ELEVATION TOP DAM: + 164.9 M.S.L.

CREST:

a. Elevation + 160.9 M.S.L.b. Type Auxiliary spillway channelc. Width 75 feet wide channeld. Length 670 foot long channele. Location Spillover Left abutmentf. Number and Type of Gates NoneOUTLET WORKS: Principal spillway (crest El. 156.5)a. Type 2 stage drop inlet with 30" diameter reinforced concrete pipe.b. Location 135 feet from left abutmentc. Entrance inverts + 130⁺ M.S.L.d. Exit inverts + 129 M.S.L.e. Emergency draindown facilities Gate at invert El. 130.25 M.S.L.HYDROMETEOROLOGICAL GAGES: None

a. Type

b. Location

c. Records

MAXIMUM NON-DAMAGING DISCHARGE: 1570 CFS

SUBJECT_____

ASSUMPTION STATE #19 DAM INSPECTION

PROJECT C227

Time of Concentration -- Tc				
(1) Description of Course of Runoff Water	(2) Slope of Course (%)	(3) Length (l) of Course (ft)	(4) Velocity of Runoff Water (v) (ft/sec)	(5) Time (sec) (3) ÷ (4)
OVERLAND-CROPLAND	2.4	4000	1.0	4000
CHANNEL	0.6	9700	2.0	4850
Sum				8850

BY D. J. M. DATE 1-79

CHKD. BY _____ DATE _____

SUBJECT _____

LOUIS BERGER & ASSOCIATES INC.

ASSUMPTION SITE #19 DAM INSPECTION

SHEET NO. A2 OF _____PROJECT C227

<u>T</u>	<u>T/T₀</u>	<u>Dimensionless ordinate (D₀)</u>	<u>Q_p x D₀</u>
0.25	0.16	0.05	27
0.50	0.31	0.17	91
0.75	0.47	0.33	203
1.00	0.63	0.65	348
1.25	0.78	0.86	460
1.50	0.94	0.95	524
1.75	1.09	0.98	524
2.00	1.25	0.88	471
2.25	1.41	0.74	396
2.50	1.56	0.60	321
2.75	1.72	0.47	251
3.00	1.88	0.38	203
3.25	2.03	0.30	161
3.50	2.19	0.24	128
3.75	2.34	0.198	106
4.00	2.50	0.155	83
4.25	2.63	0.120	64
4.50	2.81	0.096	51
4.75	2.97	0.078	42
5.00	3.12	0.064	34
5.25	3.28	0.053	28
5.50	3.44	0.040	21
5.75	3.59	0.032	17
6.00	3.75	0.027	14

Σ 4568

BY D.J.M. DATE 1-79

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A3 OF

CHKD. BY _____ DATE _____

PROJECT C227

SUBJECT _____


PRECIPITATION DATA FROM T.P. 40 (see depth duration curve overleaf)
8 HMR 35

Time	Precipitation	Δ	Rearrange
0.25	1.7	1.7	0.06
0.50	2.4	0.7	0.06
0.75	2.8	0.4	0.06
1.00	3.1	0.3	0.06
1.25	3.5	0.4	0.07
1.50	3.7	0.2	0.07
1.75	3.86	0.16	0.08
2.00	4.00	0.14	0.09
2.25	4.11	0.11	0.09
2.50	4.22	0.11	0.09
2.75	4.31	0.09	0.11
3.00	4.40	0.09	0.11
3.25	4.49	0.09	0.30
3.50	4.57	0.08	0.70
3.75	4.64	0.07	1.70
4.00	4.71	0.07	0.40
4.25	4.78	0.07	0.40
4.50	4.84	0.06	0.20
4.75	4.90	0.06	0.16
5.00	4.96	0.06	0.14
5.25	5.02	0.06	0.07
5.50	5.08	0.06	0.06
5.75	5.14	0.06	0.06
6.00	5.20	0.06	0.06

BY D. J. M. DATE 1-79
CHKD. BY _____ DATE _____

SUBJECT T.P. 40 & H.M.R. 35
DEPTH DURATION CURVE

SHEET NO. A4 OF _____
JOB NO. C227



BY D.J.M. DATE 1-79

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A5 OF

CHKD. BY _____ DATE _____

PROJECT C227SUBJECT SCS SPILLWAY DISCHARGE CALCULATIONSHydraulic:

pipe dia. 30" ²
 $A_p = 4.91 \text{ ft.}^2$
 $r = .012$
 $k_r = 1$
 $k_p = .0786$
 $L_p = 180'$

$$C_p = \frac{A_p \cdot 2g}{1 + k_r \cdot C_p}$$

$$= \frac{64.4}{1 + 1.4}$$

$$= 21.36$$

$$Q = 21.36 \times h^4$$

Width of auxiliary spillway = 75 feet

At elevation 162.57, pipe flow is 114 cfs
 and auxiliary spillway is 364 cfs

Total flow is 478 cfs

Check velocity:

Auxiliary spillway crest elevation 160.9

$$A = 75 \times 1.67 + 1.67^2 \times 3 \quad d_c = 162.57 - 160.9 = 1.67 \text{ feet}$$

$$= 133.33 \text{ ft}^2$$

$$v = \frac{364}{133.33} = 2.74 \text{ feet per second}$$

Hydrograph developed by SCS for principal spillway, indicates that peak of the flood will be reduced considerably by temporary storage above the spillway crest.

STATE New Jersey PROJECT Reservoir - Site 10
 COUNTY Montgomery DATE 12-67 CHECKED BY _____ DATE _____
 SUBJECT Re-design Of Orifice

Low-stage orifice is to be lowered 6' due to addition of Wildlife Water Control Device.

Orifice size must be reduced to give approximately the same discharge at the increased head.

$$Q_{\text{max.}} = 12 \text{ cfs (WORK PLAN)}$$

$$Q = C_u (2gh)^{1/2}$$

$$h = 159.0 - 149.9 = 9.1 \text{ Ft. use } 9'$$

$$12 = .6 a (8.025)(9)^{1/2}$$

$$12 = 14.4 a$$

$$a = 0.833$$

use 12" x 10" ORIFICE

1' wide x 10" Deep

BY D.J.H. DATE 1-79

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A6 OF

CHKD. BY DATE

PROJECT C227

SUBJECT SCS SPILLWAY DISCHARGE CALCULATIONS

COMPUTATION SHEET
SCS-222 REV 9-66

STATE N.J. PROJECT Assessment - Site 19


BY C. J. H. DATE 8/13/66 CHECKED BY D. J. H. DATE 8/13/66 JOB NO. NY 69-2010-19 R

SUBJECT Riser Crest Weir & Conduit Flow SHEET 67

Weir Flow

$$Q = C L H^{3/2}$$

$$= 3.1(15) H^{3/2}$$

$$Q = 46.5 H^{3/2}$$


Conduit Flow

$$Q = C_p h_p^{3/2}$$

$$C_p = A_p \sqrt{\frac{2g}{1 + K_r + K_p l_p}}$$

$$= 4.91 \sqrt{\frac{64.4}{1 + 1 + 1.4}}$$

$$= 4.91 \sqrt{18.9}$$

$$= 4.91 (4.35)$$

$$= 21.36$$

$$Q_{ch} = 21.36 h_p^{3/2}$$

2.5' ID Conc. Pipe

$A_p = 4.91 \text{ ft}^2$

$\eta = 0.012$

$K_r = 1$

$K_p = .00786$

$l_p = 180'$

BY DJM DATE 1-79
CHKD. BY _____ DATE _____
SUBJECT SES SPILLWAY DISCHARGE CALCULATIONS

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. 17 OF _____
PROJECT 2727

COMPUTATION SHEET
800-000 REV 000

STATE N.J. PROJECT ASSUMPTIONS - SITE 19
BY Montana DATE 8/8/66 CHECKED BY U. LEVY DATE 8-66 JOB NO. N.J. CR-2010-19
SUBJECT ORIFCE SIZE - Low STAGE SHEET _____ OF _____

$Q_{MAX} = 12 \text{ CFS}$ (WORK PLANS) ✓

High Stage 159.0
Low Stage 156.5
2.5 ✓

$Q = C a (2gh)^{1/2}$

$12 = .6 a (8.025) (2.5)^{1/2}$

$a = \frac{12}{.6 (1.58) (8.025)}$

$a = 1.58 \text{ ft}^2$ ✓

$W = \frac{3}{4} \phi = \frac{3}{4} (30) = 22.5 \text{ IN} = 1.875 \text{ ft}$ ✓

$H = 1.58 \div 1.875 = 0.84 \text{ ft} = 10 \text{ IN.}$ ✓

$a = 1.875 (.24) = 1.58$ OK/ ✓

Low Stage Weir Flow

$Q = CL H^{3/2}$
 $Q = 3.1 (1.875) (H^{3/2}) = 5.81 H^{3/2}$

Low Stage Orifice Flow:

$Q = C a (2gh)^{1/2}$
 $= 0.6 (1.58) (8.025) h^{1/2}$
 $= 7.61 h^{1/2}$

BY D.J.H. DATE 1-79

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A8 OF

CHKD. BY _____ DATE _____

PROJECT _____

SUBJECT SCS SPILLWAY DISCHARGE CALCULATIONS

RECORD DIVISION			
DATE	PROJECT	BY	CHKD.
11-15-66	SPILLWAY	D.J.H.	
SUBJECT			
AUXILIARY SPILLWAY DISCHARGE			
ELEV	h_f	g	Q_{75}
160.0	0	0	0
161.0	0.1	0.05	4
161.5	0.6	0.8	60
162.0	1.1	2.4	180
162.5	1.6	4.5	330
163.0	2.1	6.8	510
163.5	2.6	9.8	735
164.0	3.1	13.2	990

BY DJM DATE 1-79

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A9 OF _____

CHKD. BY _____ DATE _____

ASSONPICK SITE #19 DAM INSPECTION

PROJECT C227

SUBJECT SPILLWAY DISCHARGE CAPACITY AS COMPUTED BY SCS

U.S. DEPARTMENT OF AGRICULTURE BUREAU OF RECLAMATION					
STAGE DISCHARGE CURVE					
AGS-100-A-S-13					
ELEV.	LOW STAGE		RISE & FLOOD		TOTAL Q ₂ CFS
	WEIR H _{1/2} FT. Q = 5.81 M ^{3/2}	ORIFICE H _{1/2} FT. Q = 7.61 M ^{3/2}	WEIR H _{1/2} FT. Q = 46.5 M ^{3/2}	COUNTDOWN Q = 21.36 M ^{3/2}	
	H _R FT.	H _O FT.	H _R FT.	H _O FT.	Q ₂ CFS
156.5	0	0			0
156.75	0.25	.1250			0.7
157.00	0.50	.3536			2.1
157.25	0.75	.6495			3.8
157.33	0.83	.7562			4.4
157.50	1.00	1.000			5.8
158.00					7.9
158.50					9.6
159.00					11.0
159.50					28.7
160.00					59.8
160.50					110.0*
161.00					4 115.1
161.50					60 171.9
162.00					130 243.0
162.50					338 452.0
163.00					515 625.7
163.50					736 851.0
164.00					990 1107.0
164.90					1451 1569.8
Note: After is full or overflow it was determined to base the low stage discharge curve on the low stage water level at Elev. 155.7 ft. This stage is necessary.					

BY D. J. M. DATE 1-77

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A10 OF

CHKD. BY _____ DATE _____

ACCOUNT # 101 DAM INSPECTIONPROJECT C227

SUBJECT _____


STAGE / STORAGE FROM SCS

ELEV M.S.L	STORAGE (ACRE FEET)	SURCHARGE STORAGE (ACRE FEET)
155.9	455	0
156.5	490	35
157.0	520	65
158.0	582	127
159.0	650	195
160.0	726	271
160.2	735	280
161.0	805	350
162.0	890	435
163.0	985	530
164.0	1097	642

BY D. J. M. DATE 1-79
CHKD. BY DATE

SUBJECT STAGE STORAGE CURVE

SHEET NO. A11 OF
JOB NO. C227



BY D. J. M. DATE 1-79
CHKD. BY _____ DATE _____
SUBJECT _____

LOUIS BERGER & ASSOCIATES INC.

ASSUMPTION SITE # 19 DAM INSPECTION

SHEET NO. A12 OF _____
PROJECT C227

Summary of storage and discharge data for HEC-1 input

<u>Elevation</u> <u>(feet)</u>	<u>SURCHARGE STORAGE</u> <u>(ACRE FEET)</u>	<u>DISCHARGE</u> <u>(cfs)</u>
	0	0
157	65	2
158	127	8
159	195	11
160	271	60
161	350	115
162	435	243
163	530	625
164	642	1107

SUBJECT_____

ASSUMPTION SITE #19 DAM INSPECTION

PROJECT _____

BY L.B. DATE FEB '79

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A.14 OF

CHKD. BY _____ DATE _____

ASSUMPINK SITE #19 DAM INSPECTIONPROJECT C-227SUBJECT DRAWDOWN COMPUTATIONS

ELEV FT.	TOTAL STORAGE ACRE-FT	DIFF. STORAGE ACRE-FT	DISCHARGE		AVERAGE DISCHARGE ACRE-FT/DAY	DRAWDOWN TIME DAYS
			ACTUAL CFS	AVG. CFS		
155.9	455		24.4			
		95		24	47.6	2.0
154	360		23.5			
		80		22.7	45.02	1.78
152	280		21.8			
		75		21.6	42.84	1.75
150	205		21.4			
		55		20.9	41.45	1.33
148	150		20.3			
		45		19.7	39.07	1.15
146	105		19.1			
		40		18.5	36.7	1.09
144	65		17.9			
		30		17.2	34.12	.88
142	35		16.5			
		16		15.8	31.34	.51
140	19		15.0			
		9		14.2	28.17	.32
138	10		13.4			
		6		12.5	24.79	.24
136	4		11.5			
		2		10.4	20.63	.10
134	2		9.3			
		1		7.9	15.67	.06
132	1		6.4			
		1		3.2	6.35	.16
130.25	0		0			

$$Q = C A \sqrt{2gH}$$

$$= .6 (1) \sqrt{64.4 H}$$

$$= 4.8150 H^{1/2}$$

Σ 11.37 DAYS SAY 12 days.

BY DJM DATE _____
 CHKD. BY _____ DATE _____
 SUBJECT _____

LOUIS BERGER & ASSOCIATES INC.
ASSUNPINK CREEK SITE 19

SHEET NO. A-15 OF _____
 PROJECT C-227

A	ASSUNPINK SITE#18,19,4 DAM INSPECTIONS NORTH GROUP									
A	BY D.J.MULLIGAN									
A	FEBRUARY 1979									
B	150	0	15						3	
1	3									
K	0	2							1	
1	INFLOW TO SITE 19 DAM									
M	0	-1	1.77	0	1.77					
0	24									
1	0.06	0.06	0.06	0.06	0.07	0.07	0.08	0.09	0.09	0.09
1	0.11	0.11	0.30	0.70	1.70	0.40	0.40	0.20	0.16	0.14
1	0.07	0.06	0.06	0.06						
T							0.5	0.1		
U	24									
1	27	91	203	348	460	524	524	471	396	321
1	251	203	161	128	106	83	64	51	42	34
1	28	21	17	14						
X	0	0	1							
K	1									
1	ROUTING THROUGH 19									
Y										
1	1									
2	0	65	127	195	271	350	435	530	642	
3	0	2	8	11	60	115	243	625	1107	

SUB-AREA RUNOFF COMPUTATION

INFLOW TO SITE 19 DAM

ISTAQ ICOMP IECON ITAPE JPLT JPRT INAME
 2 0 0 0 0 0 1

HYDROGRAPH DATA

IHYGG IUHG IAREA SNAP TRSCA TRSPC RATIO ISNOW ISAME LOCAL
 0 -1 1.77 0.0 1.77 0.0 0.0 0 0 0

PRECIP DATA

NP STORM DAJ DAK
 24 0.0 0.0 0.0

PRECIP PATTERN

0.06 0.06 0.06 0.06 0.07 0.07 0.08 0.09 0.09 0.09
 0.11 0.11 0.30 0.70 1.70 0.40 0.40 0.20 0.16 0.14
 0.07 0.06 0.06 0.06

LOSS DATA

STRRR CLYKR RTIOL ERAIN STRKS RTIOK STRIL CRSTL ALSMX RTIMP
 0.0 0.0 1.00 0.0 0.0 1.00 0.50 0.10 0.0 0.0

GIVEN UNIT GRAPH, NUHGC= 24

27. 91. 203. 348. 460. 524. 524. 471. 396. 321.
 251. 203. 161. 128. 106. 83. 64. 51. 42. 34.
 28. 21. 17. 14.

UNIT GRAPH TOTALS 4568. CFS OR 1.00 INCHES OVER THE AREA

RECESSION DATA

STRTO= 0.0 GRCSN= 0.0 RTIOR= 1.00

END-OF-PERIOD FLOW

TIME RAIN EXCS COMP Q
 1 0.06 0.00 0.
 2 0.06 0.00 0.

BY DJM DATE _____
CHKD. BY _____ DATE _____
SUBJECT _____

LOUIS BERGER & ASSOCIATES INC.
ASSUNPINK CREEK SITE #19

SHEET NO. A16 OF _____
PROJECT C-227

3	0.06	0.00	0.
4	0.06	0.00	0.
5	0.07	0.00	0.
6	0.07	0.00	0.
7	0.08	0.00	0.
8	0.09	0.04	1.
9	0.09	0.06	5.
10	0.09	0.06	15.
11	0.11	0.08	34.
12	0.11	0.08	62.
13	0.30	0.27	104.
14	0.70	0.67	173.
15	1.70	1.67	316.
16	0.40	0.37	558.
17	0.40	0.37	903.
18	0.20	0.18	1293.
19	0.16	0.13	1613.
20	0.14	0.11	1811.
21	0.07	0.05	1850.
22	0.06	0.04	1755.
23	0.06	0.04	1573.
24	0.06	0.04	1369.
25	0.0	0.0	1158.
26	0.0	0.0	976.
27	0.0	0.0	809.
28	0.0	0.0	668.
29	0.0	0.0	550.
30	0.0	0.0	442.
31	0.0	0.0	353.
32	0.0	0.0	282.
33	0.0	0.0	225.
34	0.0	0.0	181.
35	0.0	0.0	145.
36	0.0	0.0	113.
37	0.0	0.0	88.
38	0.0	0.0	63.
39	0.0	0.0	32.
40	0.0	0.0	21.
41	0.0	0.0	13.
42	0.0	0.0	8.
43	0.0	0.0	5.
44	0.0	0.0	3.
45	0.0	0.0	2.
46	0.0	0.0	1.
47	0.0	0.0	0.
48	0.0	0.0	0.
49	0.0	0.0	0.
50	0.0	0.0	0.
51	0.0	0.0	0.
52	0.0	0.0	0.
53	0.0	0.0	0.
54	0.0	0.0	0.
55	0.0	0.0	0.
56	0.0	0.0	0.
57	0.0	0.0	0.
58	0.0	0.0	0.
59	0.0	0.0	0.
60	0.0	0.0	0.
61	0.0	0.0	0.
62	0.0	0.0	0.
63	0.0	0.0	0.

64	0.0	0.0	0.
65	0.0	0.0	0.
66	0.0	0.0	0.
67	0.0	0.0	0.
68	0.0	0.0	0.
69	0.0	0.0	0.
70	0.0	0.0	0.
71	0.0	0.0	0.
72	0.0	0.0	0.
73	0.0	0.0	0.
74	0.0	0.0	0.
75	0.0	0.0	0.
76	0.0	0.0	0.
77	0.0	0.0	0.
78	0.0	0.0	0.
79	0.0	0.0	0.
80	0.0	0.0	0.
81	0.0	0.0	0.
82	0.0	0.0	0.
83	0.0	0.0	0.
84	0.0	0.0	0.
85	0.0	0.0	0.
86	0.0	0.0	0.
87	0.0	0.0	0.
88	0.0	0.0	0.
89	0.0	0.0	0.
90	0.0	0.0	0.
91	0.0	0.0	0.
92	0.0	0.0	0.
93	0.0	0.0	0.
94	0.0	0.0	0.
95	0.0	0.0	0.
96	0.0	0.0	0.
97	0.0	0.0	0.
98	0.0	0.0	0.
99	0.0	0.0	0.
100	0.0	0.0	0.
101	0.0	0.0	0.
102	0.0	0.0	0.
103	0.0	0.0	0.
104	0.0	0.0	0.
105	0.0	0.0	0.
106	0.0	0.0	0.
107	0.0	0.0	0.
108	0.0	0.0	0.
109	0.0	0.0	0.
110	0.0	0.0	0.
111	0.0	0.0	0.
112	0.0	0.0	0.
113	0.0	0.0	0.
114	0.0	0.0	0.
115	0.0	0.0	0.
116	0.0	0.0	0.
117	0.0	0.0	0.
118	0.0	0.0	0.
119	0.0	0.0	0.
120	0.0	0.0	0.
121	0.0	0.0	0.
122	0.0	0.0	0.
123	0.0	0.0	0.
124	0.0	0.0	0.

A

SHEET NO. A-17 OF
PROJECT C-227

HYDROGRAPH ROUTING

ROUTING THROUGH 19

ROUTING	INSTRG	IComp	IECON	ITAPE	JPLT	JPRT	INAME
0	1	0	0	0	0	0	1
ROUTING DATA							
GLOSS	CLOSS	Avg	IRIS	ISAME			
0.0	0.0	0.0	1	0			
NSTPS	NSTD	Lag	AMSKK	X	TSK	STORA	
1	0	0	0.0	0.0	0.0	0.0	

STORAGE =
OUTFLOW =

STORAGE=	0.	127.	195.	271.	350.	435.	530.	642.	0.
OUTFLOW=	0.	8.	11.	50.	115.	243.	625.	1107.	0.
	TIME	POP	STOR	AVG IN	POP OUT				
	1	0.	0.	0.	0.				
	2	0.	0.	0.	0.				
	3	0.	0.	0.	0.				
	4	0.	0.	0.	0.				
	5	0.	0.	0.	0.				
	6	0.	0.	0.	0.				
	7	0.	0.	0.	0.				

BY DJM DATE _____
CHKD. BY _____ DATE _____
SUBJECT _____

LOUIS BERGER & ASSOCIATES INC.

ASSUMPTION CREEK SITE #19

SHEET NO. A18 OF _____
PROJECT C-227

8	0.	0.	0.
9	0.	3.	0.
10	0.	10.	0.
11	1.	24.	0.
12	2.	48.	0.
13	3.	83.	0.
14	6.	138.	0.
15	11.	245.	0.
16	20.	437.	1.
17	35.	750.	1.
18	58.	1098.	2.
19	88.	1453.	4.
20	123.	1712.	8.
21	161.	1831.	9.
22	198.	1802.	13.
23	232.	1666.	35.
24	261.	1474.	54.
25	286.	1264.	71.
26	307.	1067.	85.
27	323.	892.	96.
28	336.	739.	106.
29	347.	609.	113.
30	355.	496.	122.
31	360.	397.	130.
32	364.	317.	136.
33	366.	254.	140.
34	368.	204.	142.
35	368.	163.	142.
36	368.	129.	142.
37	367.	100.	141.
38	366.	75.	139.
39	364.	47.	136.
40	362.	27.	132.
41	359.	17.	129.
42	357.	11.	125.
43	354.	7.	122.
44	352.	4.	118.
45	350.	2.	115.
46	347.	1.	113.
47	345.	1.	112.
48	343.	0.	110.
49	341.	0.	108.
50	338.	0.	107.
51	336.	0.	105.
52	334.	0.	104.
53	332.	0.	102.
54	330.	0.	101.
55	328.	0.	99.
56	326.	0.	98.
57	324.	0.	97.
58	322.	0.	95.
59	320.	0.	94.
60	318.	0.	93.
61	316.	0.	91.
62	314.	0.	90.
63	312.	0.	89.
64	310.	0.	87.
65	309.	0.	86.
66	307.	0.	85.
67	305.	0.	84.
68	303.	0.	82.

69	302.	0.	81.
70	300.	0.	80.
71	298.	0.	79.
72	297.	0.	78.
73	295.	0.	77.
74	293.	0.	76.
75	292.	0.	75.
76	290.	0.	74.
77	289.	0.	72.
78	287.	0.	71.
79	286.	0.	70.
80	285.	0.	69.
81	283.	0.	68.
82	282.	0.	67.
83	280.	0.	66.
84	279.	0.	66.
85	278.	0.	65.
86	276.	0.	64.
87	275.	0.	63.
88	274.	0.	62.
89	272.	0.	61.
90	271.	0.	60.
91	270.	0.	59.
92	269.	0.	59.
93	268.	0.	58.
94	266.	0.	57.
95	265.	0.	56.
96	264.	0.	55.
97	263.	0.	55.
98	262.	0.	54.
99	261.	0.	53.
100	260.	0.	53.
101	258.	0.	52.
102	257.	0.	51.
103	256.	0.	51.
104	255.	0.	50.
105	254.	0.	49.
106	253.	0.	49.
107	252.	0.	48.
108	251.	0.	47.
109	250.	0.	47.
110	249.	0.	46.
111	248.	0.	45.
112	247.	0.	45.
113	247.	0.	44.
114	246.	0.	44.
115	245.	0.	43.
116	244.	0.	43.
117	243.	0.	42.
118	242.	0.	41.
119	241.	0.	41.
120	240.	0.	40.
121	240.	0.	40.
122	239.	0.	39.
123	238.	0.	39.
124	237.	0.	38.
125	236.	0.	38.
126	236.	0.	37.
127	235.	0.	37.
128	234.	0.	36.
129	233.	0.	36.

BY DJM DATE _____
 CHKD. BY _____ DATE _____
 SUBJECT _____

LOUIS BERGER & ASSOCIATES INC.
ASSUNPINK CREEK SITE #19

SHEET NO. A19 OF _____
 PROJECT C-227

130	233.	0.	35.
131	232.	0.	35.
132	231.	0.	34.
133	231.	0.	34.
134	230.	0.	33.
135	229.	0.	33.
136	228.	0.	33.
137	228.	0.	32.
138	227.	0.	32.
139	226.	0.	31.
140	226.	0.	31.
141	225.	0.	30.
142	225.	0.	30.
143	224.	0.	30.
144	223.	0.	29.
145	223.	0.	29.
146	222.	0.	29.
147	222.	0.	28.
148	221.	0.	28.
149	220.	0.	27.
150	220.	0.	27.

SUM 8951.

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	142.	124.	82.	60.	8951.
INCHES		0.65	1.72	1.96	1.96
AC-FT		62.	162.	185.	185.

COMBINE HYDROGRAPHS

COMBINE HYDROGRAPHS FOR SITES 18&19

ISTAG	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME
0	2	0	0	0	0	1

SUM OF 2 HYDROGRAPHS AT 0

0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	1.	1.	2.	3.	6.	9.	13.	43.
73.	137.	203.	252.	291.	322.	336.	345.	343.	340.
336.	331.	324.	315.	306.	296.	285.	275.	263.	252.
241.	231.	221.	211.	202.	195.	189.	182.	176.	171.
165.	161.	156.	156.	153.	151.	146.	146.	144.	141.
139.	137.	135.	133.	131.	129.	127.	125.	123.	121.
119.	117.	115.	113.	111.	110.	108.	106.	105.	103.
101.	100.	98.	97.	95.	94.	92.	91.	89.	88.
87.	85.	84.	83.	82.	80.	79.	78.	77.	76.
75.	73.	72.	71.	70.	69.	68.	67.	66.	65.
64.	63.	62.	61.	61.	60.	59.	58.	57.	56.
55.	55.	54.	53.	52.	51.	51.	50.	49.	48.
48.	47.	46.	46.	45.	44.	44.	43.	42.	42.
41.	41.	40.	39.	39.	38.	38.	37.	37.	36.

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	345.	280.	150.	107.	16057.
INCHES		0.87	1.87	2.09	2.09
AC-FT		139.	298.	332.	332.